







■ XXY160-5-MC40-B28
 XXY160-5-MC41-B28



■ XXY200-5-MC40-B28
 XXY200-5-MC41-B28






■ XXY200-5-MC40-S5ZC1
 XXY200-5-MC40-S5ZC2
 XXY200-5-MC41-S5ZC1
 XXY200-5-MC41-S5ZC2






S5ZC1: 50W Servo Motor Connector
PCD45-Φ30-Φ8-M3

S5ZC2: 50W Servo Motor Connector
PCD46-Φ30-Φ8-M4



■ XXY250-7-MC40-B42
 XXY250-7-MC41-B42





■ XXY250-7-MC40-S10C1
 XXY250-7-MC40-S10C2
 XXY250-7-MC41-S10C1
 XXY250-7-MC41-S10C2






S10C1: 100W Servo Motor Connector
PCD45-Φ30-Φ8-M3

S10C2: 100W Servo Motor Connector
PCD46-Φ30-Φ8-M4



■ XXY300-7-MC40-B42
 XXY300-7-MC41-B42



■ XXY300-7-MC40-S10C1
 XXY300-7-MC40-S10C2
 XXY300-7-MC41-S10C1
 XXY300-7-MC41-S10C2



S10C1: 100W Servo Motor Connector
 PCD45- $\Phi 30$ - $\Phi 8$ -M3

S10C2: 100W Servo Motor Connector
 PCD46- $\Phi 30$ - $\Phi 8$ -M4

